

# General Environmental Incident Summary

**Incident:** 5238      **Date/Time Notice:** 9/26/2016      2012      **DEM Incident No:**  
**Responsible Party:** NUVERRA ENVIRONMENTAL SOLUTIONS  
**Date Incident:** 9/26/2016      **Time Incident:** 1630      **Duration:** 2 hours  
**County:** McKenzie      **Twp:** 150      **Rng:** 98      **Sec:** 9      **Qtr:**  
**Lat:** 47.85081      **Long:** -103.19460      **Method:** Interpolation from map  
**Location Description:** JJ SWD . NORTH ON 1806 EAST ON 30TH ST

**Submitted By:** Les Taylor      **Affiliation:** Manager  
**Address:** 3711 4th Ave NE  
**City:** Watford City      **State:** ND      **Zip:** 58854

## Received By:

**Contact Person:** Les Taylor  
3711 4TH AVE NE  
Watford City, ND 58854

**Distance Nearest Occupied Building:** 2 Miles      **Release Contained:** Yes

**Type of Incident:** Vehicle Accident

**Description of Released Contaminant:** PRODUCED SALT WATER

**Volume Spilled:** 210.00 gallons      **Ag Related:** No

**EPA Extremely Hazardous Substance:** No      **Reported to NRC:** Unknown

## Cause of Incident:

DRIVER STOPPED ON ROAD WAITING TO GET INTO DISPOSAL WAS TOO CLOSE TO EDGE OF ROAD AND PUP TRAILER ROLLED OFF SHOULDER OF ROAD.

## Risk Evaluation:

NONE

**# of Fatalities:** 0      **# of Injuries:** 0      **Affected Medium:** 03 - soil

## Potential Environmental Impacts:

SOIL IMPACT NO OTHER IMPACT

## Action Taken or Planned:

WATER WAS VACUUMED OFF GROUND AND A ONE CALL WAS MADE AND WE WILL THAN EXCAVATE THE GROUND AND REPLACE THE SOIL.

**Wastes Disposal Location:** WATER WILL BE TAKEN TO RINK SWD  
SOLIDS WILL BE TAKEN TO NUVERRA ENVIRONMENTAL  
TREATMENT CENTER

## Agencies Involved:

## **Updates**

---

**Date:** 9/26/2016    **Status:** Reviewed - Follow-up Required

**Author:** Stockdill, Scott

**Updated Volume:**

**Notes:**

According to the incident summary, this spill impacted the surrounding area. Follow-up is necessary to ensure proper cleanup.

---

**Date:** 9/27/2016    **Status:** Inspection

**Author:** Crowdus, Kory

**Updated Volume:**

**Notes:**

On location 9/27/2016, at 9:38 a.m. Release was on the east side of lease road entering SWD facility. Impacted area is approximately 10 X 200 feet and has been marked with stakes and paint. I spoke to contact about sampling once soil has been removed. More follow-up is required.